

1. Fill a glass 50/50 with ice and water slush.
2. Submerge thermometer so water level reaches metal indentation on stem.
3. If temperature does not read 32°F, use a small wrench to turn the calibration nut until the thermometer reads 32°F

Kansas Department of Health and Environment
Bureau of Consumer Health
1000 SW Jackson, Suite 200
Topeka, KS 66612-1274
(785) 296-5600
www.kdhe.state.ks.us

